

OZITO PORTABLE ELECTRIC BLOWER
Model No. OZBL1800WA

## **IDENTIFICATION:**

All units marked with the following batch numbers are covered by this recall.

The batch number label is located near the air intake vent. The product was sold through Bunnings stores nationally.



Batch Numbers
0901A, 0901C, 0903E, 0905C, 0906D,
0907D, 0908D
1003, 1008, 1009, 1010, 1011, 1012
1102, 1103, 1104, 1105, 1107, 1108, 1109,
1111, 1112
1202, 1204, 1205, 1206, 1207, 1208, 1209,
1211, 1212





**OZBL1800WA on Data Label** 

## **DEFECTS:**

The impeller can break during use and rupture the casing, giving access to live parts and releasing sharp objects at high speed.

## **HAZARD:**

The defect poses a risk of electric shock and/or injuries from sharp objects at high speed. The defect has occurred and caused a number of injuries to consumers.

## What should I do?

- Stop using the blower immediately and unplug it from the power point.
- Check the batch number of the blower (as shown above) to see if you have the recalled product.
- If so, contact Ozito on 1800 069 486 and then visit your nearest Bunnings store to arrange an upgrade (https://www.bunnings.com.au/ozito-power-x-change-18v-blower-kit\_p3381084) or a refund.
- For further information, email Ozito at enquiries@ozito.com.au

See <u>www.recalls.gov.au</u> for Australian Product Recall Information See <u>www.consumeraffairs.govt.nz</u> for New Zealand Product Recall Information